

**Project:** GLASS WATERFALLS

**Title:** MERIT HQ

**Date:** MARCH 2011



**The problem:** water running down the waterfalls is not filling all the glass surfaces at the lowest part of the glass, especially at the edges of the glass and hard to be pushed at the top part. The water is not covering the entire glass surface.

**The solution:** To solve the issue, the glass was treated using Glass Renovator, which safely and effectively removes light build-up of bonded inorganic contaminants including limescale, metal oxides and other inorganic contaminants from glass. This way all microscopic contamination was eliminated and the water is covering the entire area. ClearShield Glass Protect was also used at the top part of the glass, making the surface smoother thus the water coming down from the water container was easily pushed over the entire surface.

**The result:** The calming effect of the water sound is maximized as well as the appearance of the water fall is more eye-catching as water covers all the edges. Even after few months of the application, the result was still the pleasing.

